

Tatkraft

COLUMBIA DIGITAL POCKET SCALE

INSTRUCTION FOR USE




ISO 9001:2008

art. 20344

■ LCD DISPLAY




■ TO INSTALL OR REPLACE BATTERY



1×3V CR2032 lithium batteries (included).
Remove isolation sheet before use.

1. Take out used batteries, with the aid of a sharp object If needed.
2. Install new batteries by putting one side of the battery down first and pressing down the other side. Pl LCD ease observe the polarity!


■ TO OPERATE SCALE



1. Please put the scale on a hard and flat surface.
2. Press and release **ON/OFF** button to turn on the unit.
3. Wait until display prompts to «0.0» before starting weighing.
4. You can start weighing now. Please always try to place the weighing object at the center of the weighing platform.

■ TO CONVERT WEIGHT UNIT

During the course of weighing, you can always button **UNIT** to convert weight unit (gram, oz, dwt or ozt).




■ BUTTONS ILLUSTRATION

- UNIT** Unit conversion
- ON/OFF** Turn the scale
- Z/T** Zero or Tare function

■ «ZERO» OR «TARE» FUNCTION

To weigh different loads consecutively without removing loads from the scale. Put first load on the scale, get weight reading. Press button **Z/T** to reset the LCD reading to «0.0» before adding next load. You can repeat this operation.



«ZERO» FUNCTION

When total sum of all the weighed ingredients on the scales is less than or equal to 200 g.

LCD will show «0.0g» each time is **Z/T** pressed. Icon ● will appear on the lower left corner of LCD, indicating **ZERO** function is active.

Maximum weight capacity remains unchanged.


«TARE» FUNCTION

When total sum of all the weighed ingredients on the scales is more than 200 g.


LCD will show «0.0g» each time is **Z/T** pressed. Icon **TARE** will appear on the upper left corner of LCD, indicating **TARE** function is active.

Maximum weight capacity is reduced by total weight of all loads.

By pressing **Z/T** you can see the total weight of all loads on the scale. If you want to weigh more loads, just press **Z/T** to reset LCD reading to «0.0g» again.




■ AUTO SHUT OFF



Auto shut-off occurs if display shows «0» or shows the same weight reading for 2 minutes.

■ MANUAL SHUT OFF



To maximize battery life, always press button **ON/OFF** again to turn off the scale after using.

■ WARNING INDICATORS



Replace new battery.



Scale overload. Remove item to avoid damage. Maximum weight capacity is indicated on the scale.

■ CLEANING AND CARE

1. Clean the scale with a slightly damp cloth. **DO NOT** immerse the scale in water or use chemical / abrasive cleaning agents.
2. The scale is high precision device. It is delicately built and extremely sensitive. Please avoid dropping the unit or subject the unit to violent impact which will damage it.